

---

Message

---

**From:** Tinger, John [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=B6B7405A2BA548B5886C18A0A64675CC-JTINGER]  
**Sent:** 12/2/2021 2:03:47 AM  
**To:** Kurano, Matthew [matthew.kurano@doh.hawaii.gov]; Nagaue, Gavin [Gavin.Nagaue@doh.hawaii.gov]  
**Subject:** Inspection report / Kohanaiki Community Association  
**Attachments:** 2021-11-21 Kohanaiki NPDES Compliance Inspection Report.pdf

---

Matt- just as FYI attached is my inspection report in response to a compliant. Complaint obviously a disgruntled former employee, but I was kinda forced into follow-up. All looks very good, although they should do a better job of scrubbing the odors – not septic bad, but noticeable, if you get further complaints. No merit to the complaint at all.

**Subject:** Kohanaiki Community Association

Inspection report responding to citizen's complaint. No issues were found.

“The resort waist water plant is along side the access road to County Beach Park called Kohanaiki Beach Park{pine trees}. There every day you can smell shit raw sewer coming from there plant which is not the proper facility fort such a large community. There is no scads system and it doesn't have the proper cleaning process or an aerator to control the waist of anaerobic by product with no chlorinating process or ultraviolet lighting and no filtration system wich recovers any non portable water. This is a major health hazard which is in native environment which should be addressed immidiatley for failure to have the proper sewing system. THE SMELL IS CONTROLLABLE THREW ARATION AND PROPER WAISTING. EX PLANT OPERATOR AT KAILUA KONA AIRPORT WAIST WATER PLANT! THIS IS HAWAII NOT THE MAINLAND”

John Tinger

US EPA | Wastewater Enforcement  
75 Hawthorne St (ENF 3-1) | San Francisco CA 94105  
(415) 972-3518 | Cell (415) 420-2217